03500.007695.4 <u>PATENT</u>

# IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	
	: Examiner: Nhan T. Tra	ın
Katsumi Azusawa, et al.	)	
	: Group Art Unit: 2622	
Appl. No.: 10/698,367	)	
	: Confirmation No.: 116	0
Filed: November 3, 2003	)	
	:	
For: IMAGE PICKUP DEVICE AND	)	
APPARATUS INCLUDING VIBRATION	:	
CORRECTION MEANS	)	
	:	
Patent No.: 7,388,604 B2	)	
	:	
Issued: June 17, 2008	) November 25, 2008	

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

# REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However,

the Commissioner is authorized to charge any underpayment or credit any overpayment to

Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by

telephone at (202) 530-1010. All correspondence should continue to be directed to our

address given below.

Respectfully submitted,

/Daniel S. Glueck/

Daniel S. Glueck Attorney for Patentees Registration No. 37,838

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

Facsimile: (212) 218-2200

DSG/jjr

Form #33 - 2 -

# UNITED STATES PATENT AND TRADEMARK OFFICE. CERTIFICATE OF CORRECTION

7.388,604 B2 PATENT NO. :

DATED : June 17, 2008

INVENTOR(S) : Katsumi Azusawa, et al. Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# COLUMN 2:

Line 20, "pickup-means" should read --pickup means--.

#### COLUMN 3:

Line 23, "operation performed." should read -- operation .--.

#### COLUMN 5:

Line 15, "detectors." should read --detectors--.

### COLUMN 7:

Line 27, "If it" should read -- It --, and "It is" should read -- If it is --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) FCHS\_WS 2671266 v1

PATENT NO. 7,388,604 B2

No. of add'l. copies @ 30¢ per page

